



**Looking Downstream at Dutch Bill Creek
Dam has been removed and creek restoration has
started.**

Photo taken October 2, 2009



Dutch Bill Fish Passage Program: Looking at the left bank where bridge will be set

Photo taken October 6, 2009



Looking downstream at foundation of bridge on the right bank

Photo taken October 6, 2009



Photo #2: Looking downstream at the right bank

Photo taken October 6, 2009



Installing the first rock weir below the Market St. Culvert

Photo taken October 5, 2009



Photo # 2 of rock weir below the Market St. Culvert

Photo taken October 6, 2009